

**From:** [Miller, Garyg](#)  
**To:** [Lister, Melody](#)  
**Cc:** [Walters, Donn](#); [Sanchez, Carlos](#)  
**Subject:** San Jacinto Repairs Poster & Slide  
**Date:** Thursday, May 05, 2016 1:01:00 PM  
**Attachments:** [Cap Repair Dec 2015 - from San Jacinto TCRA Armored Cap Maintenance Completion Report 26012016 EPA \(00000002\).pdf](#)  
[Cap Repair Map Dec 2015 - from San Jacinto TCRA Armored Cap Maintenance Completion Report 26012016 EPA \(00000002\)-2.pdf](#)  
[Eastern Cell Probing and Repair Areas - from TCRA Cap Probing Maintenance Completion Report 04182016.pdf](#)  
[Pic of Repairing Cap Dec 2015 - from San Jacinto TCRA Armored Cap Maintenance Completion Report 26012016 EPA \(00000002\).bmp](#)  
[Pic of Eastern cell Repair - from TCRA Cap Probing Maintenance Completion Report 04182016.bmp](#)  
[Pic of Completed 12-2015 Repair at Low Tide - from SanJac Low Tide Visual Inspection 20160224.pdf](#)

---

Melody,

Here are the maps showing the San Jacinto cap repair areas. Please combine these into one poster & slide for showing recent repairs for the open house meeting scheduled for 5/25/16. Just show the repair areas from the Eastern Cell ... file, not the probing locations. Also please include the pictures as inserts if they fit, and as a separate poster & slide if they don't.

Thanks,

Gary Miller  
Remedial Project Manager  
EPA Region 6 – Superfund Division (6SF-RA)  
214-665-8318  
[miller.garyg@epa.gov](mailto:miller.garyg@epa.gov)



9768255